I.

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

| GEN | ERAL INFORMATION | | |
|-----|--|--|--|
| 1. | Report Time Period: From (mo./yr.) To (mo./yr.) 12/92 | | |
| 2. | DOGM File Number: M /037 /001 | | |
| 3. | Mine Name: Lisbon Mine | | |
| 4. | Mineral(s) Mined: <u>Uranium (Ceased operation Sept. 1988)</u> | | |
| 5. | Legal Description (Location of Lands Affected): | | |
| | 1/4,1/4, Section 21, Township 29S, Range 24E | | |
| | 1/4,1/4, Section, Township, Range | | |
| | 1/4,1/4, Section, Township, Range | | |
| 6. | Name of Operator or Company: Rio Algom Mining Corp. | | |
| 7. | Permanent Address: Lisbon Mine | | |
| | La Sal Route | | |
| | Moab, Utah 84532 | | |

| | Name: Frank Fossey Title: Radiation Safety Officer | | |
|----|---|--|--|
| | | | |
| | Address: <u>Lisbon Mine</u> , <u>LaSal Rt.</u> , <u>Moab</u> , <u>Utah 84532</u> Phone: (801) 686-2215 | | |
| | Please check if any of the above information has changed since previous year. | | |
| | MINING AND RECLAMATION | | |
| | Was the mine active during the past year? Yes ☐ No 🗷 | | |
| 2. | If active, how much ore or mineral was mined? | | |
| 3. | How much new or additional acreage was affected during past year?0 | | |
| 1. | Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. | | |
| | See Attachment One | | |
| | | | |
| | | | |
| 5. | How much acreage was reclaimed during past year? 2 acres | | |
| 5. | Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. See Attachment One | | |

| 7. | 7. What is the total disturbed acreage at years end? <u>About 3 acres</u> | | |
|---------------------|--|--|--|
| 8. | Briefly summarize mining and reclamation planned for the upcoming year. See Attachment One | | |
| | | | |
| NOTE: | Section III., "Additional Information | tion" applies only to <u>large mining operations</u> . | |
| III. <u>ADDITIO</u> | NAL INFORMATION | | |
| 1. | An updated surface facilities map should be attached if there have been sign changes since the previous map was submitted. | | |
| 2. | Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached. | | |
| IV. <u>SIGNATU</u> | JRE REQUIREMENT | | |
| I here | by certify that the foregoing is tr | ue and correct. | |
| | Name (Typed or Print): | Frank Fossey | |
| | Title of Operator: | Radiation Safety Officer | |
| | Signature of Operator: | Frut Luj | |
| | Date: <u>January 22, 1993</u> | <u>'</u> | |
| jb MR-AR | | | |


ATTACHMENT 1

- II. MINING AND RECLAMATION- Numbers 4,6 and 8
- 4. Materials used for reclamation of our tailings impoundments were taken from borrow areas 2,4,10 and 11, as approved by the BLM.

#2-43,016 bcy clay. #4- 72,216 bcy clay. #10- 98640 bcy silt. #11- 103,728 bcy silt.

Borrow areas 10 and 11 were newly disturbed areas and represent 9.3 acres and 13.2 acres respectively.


- 6. The Radon attenuation cover was completed on the Lower tailings impoundment. About 80% of the work required to change the outslope of the lower tailings embankment from a 3:1 to a 5:1 slope was completed. Reclamation of our vent shaft area (DOGM) was completed except for re-seeding.
- 8. During 1993 we plan to complete a second evaporation pond on the lower tailings impoundment. We plan to re-seed the vent shaft area as soon as the weather allows this spring, to complete the reclamation of this area.



Rio Algom Mining Corp.

January 22, 1993

Mr. D. Wayne Hedberg
Permit Supervisor
State of Utah, Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203



JAN 2 5 1993

DIVISION OF OIL GAS & MINING

Re: Annual Report (form MR-AR) for 1992

Dear Mr. Hedberg:

As required by Rules R647-003-116 and R647-004-121 of the Division's Amended and New Rules, Minerals reclamation Program, our completed Form MR-AR is enclosed for your records. The map submitted show the relative location of borrow areas 10 and 11, first used during 1992.

Please change the name of our contact person from Robert Pattison to Frank Fossey, Radiation Safety Officer.

If you have any questions or require additional information please (801) 686-2215.

Sincerely,

Frank Fossey

Radiation Safety Officer RAMC-Lisbon Operation